

Work Order No: 60456

Work Order	Description	Sced Date	S	H
1: 02-60456-0	Capital Tracking Work Order for addition of primary superheater tubing in both units.		R	Y
2: 02-60456-1	INSTALL TEMPORARY POWER ON THE 9TH AND 14TH FLOORS OF THE BOILER FOR BOILER OVER-FIRE AIR MODS.	01/06	S	Y
3: 02-60456-2	TIME EXPENDED FOR GARY SPERRY TO REMOVE SOOTBLOWER CAB INTERFERENCES FOR NEW SUPERHEATER UPRATE PROJ.		C	Y
4: 02-60456-3	TIME EXPENDED ON 1/7/03 FOR TWO ELECTRIC SHOP APPRENTICES TO HELP GARY SPERRY.	01/07	C	Y
5: 02-60456-4	REMOVE INTERFERING GUTTER FOR NEW OVER FIRE AIR DUCTWORK AND REWORK IN CONDUIT.	01/07	S	Y
6: 02-60456-5	ASSIST WITH WIRING ON BOILER OVER-FIRE AIR PROJECT DURING U1 OUTAGE. WILL REQUIRE PRE-OUTAGE WORK.		R	Y
7: 02-60456-6	SEND OUT FOR REBUILD, BREAKER, 80 AMPS, 3 POLES, 600 VOLT MOLDED CASE, WESTINGHOUSE #HFB3080.		I	N

SELECTION ?

Page 1. 24 records were identified.

Work Order No: 60456

Work Order	Description	Sced Date	S	H
1: 02-60456-7	INSTALL SCAFFOLDING AS PER DARWIN BILLS NEEDS AND INSTRUCTIONS, CONTACT DARWIN		R	N
2: 02-60456-8	UNIT 1 PREOUTAGE: DISCONNECT AND REMOVE ELECTRICAL FROM N/S 9TH FL WALL BLOWERS.		R	Y
3: 02-60456-9	REPBUILD AND/OR REPAIR 0050.0 AMP BREAKER.		C	N
4: 02-60456-10	UNIT 1 "OVER-FIRE CONTRACTOR COST TRACKER" (FOR PHIL HAILES)		R	Y
5: 02-60456-11	PROVIDE I&C SUPPORT IN OVER FIRE AIR PROJECT. TUBING, WIRING, INSTALLATION AND TESTING WILL BE		C	Y
6: 02-60456-12	UNIT 1 "OVER-FIRE CONTRACTOR COST TRACKER" (FOR BRET KENT) FOR SAFEWAY SCAFFOLD		R	Y
7: 02-60456-13	PROVIDE ELECTRICAL SUPPORT OF THE OVER FIRE AIR PROJJECT. REMOVE LIGHTS ETC.		R	Y

SELECTION ?

Page 2. 24 records were identified.

Work Order No: 60456

Work Order	Description	Sced Date	S	H
1: 02-60456-14	TIME EXPENDED FOR OPERATORS ASSISTING PHIL HAILES DURING THE UNIT OUTAGE.		R	Y
2: 02-60456-15	RETURN PRINTED OUTPUT BOARD TO FOXBORO FOR REPAIR/REPLACEMENT.		I	Y
3: 02-60456-16	UNIT 1 "OVER-FIRE COST TRACKER" FOR BOILER PERFORMANCE TESTING, (AARON NISSON)		R	Y
4: 02-60456-17	UNIT 1 "OVER-FIRE CONTRACTOR COST TRACKER" (FOR KEN NIELSON) FOR CONTROLS INSTALLATION		R	Y
5: 02-60456-18	FABRICATE DOOR FRAME FOR NEW OVERFIRE AIR DOORS. (PHIL HAILES)		R	Y
6: 02-60456-19	UNIT 1 "OVER-FIRE CONTRACTOR COST TRACKER" (FOR KEN NIELSON) FOR MATERIALS USED		R	Y
7: 02-60456-20	UNIT 1 "OVER-FIRE CONTRACTOR COST TRACKER" (FOR PHIL HAILES) FOR WINDBOX DUCT INSTALLATION		R	Y

SELECTION ?

Page 3. 24 records were identified.

Work Order No: 60456

Work Order	Description	Sced Date	S	H
1: 02-60456-21	INSTALL TEMP. POWER IN THE UNIT TWO BOILER AREA AS IT WAS IN THE UNIT ONE BOILER FOR THE OVER FIRE		R	N
2: 02-60456-22	RETROFIT BOILER VENT FAN 44 AND DUCT WORK IMPACTED BY OVERFIRE AIR MODIFICATION		R	Y
3: 02-60456-23	UNIT 1 "OVER-FIRE CONTRACTOR COST TRACKER" (FOR PHIL HAILES) FOR HVAC DUCT RELOCATION		R	Y

SELECTION ?

Page 4. 24 records were identified.